




Troubleshooting Guide for the ST160 Foam Injector & ST75/175 Foam Lance



PLEASE NOTE

The Suttner range of ST160 injectors will **not** work if:

- A K Series injector is fitted, as it won't work with the ST75. An ST72 or the ST75.1 foam lances are required instead
- There is already a chemical injector fitted to the pressure washer/system.
- If the water temperature when foaming exceeds 50°C. (upto 90°C on rinse)
- The hose is wound onto a hose reel. *(The hose needs to be fully unwound for the injector to work correctly.)*
- The hose has been joined to another hose.
- If there is some sort of vario-press or other pressure adjuster in the system.

Flowjet Cleaning Equipment LTD

Unit 4, Gatebeck Farm, Gatebeck, Kendal, LA8 0HW, United Kingdom

Tel: 015395 66193 | Email: sales@flowjet.co.uk | flowjet.co.uk